



Notice to Mariners No. 10 of 2019

Waterford Estuary Chart No. 2046

To all vessels, pleasure craft users, seafarers and fishery organisations.

Bolton Rock buoy out of position

VOID

All Mariners are hereby advised that the Bolton Rock buoy, Fl (2) R 4s, in regular position 52° 15.748'N 007° 01.967'W (off Belview Container Berth), has been displaced approximately 100 metres upstream of its charted position.

All vessels navigating in the area should proceed with caution. This Notice will be withdrawn when the buoy is reinstated.

Captain Darren Doyle
Harbour Master